

# AIP SUPPLEMENT 046/2022

## UNITED KINGDOM



UK Aeronautical Information Services  
NATS Swanwick  
Room 3115  
Sopwith Way  
Southampton SO31 7AY  
aissupervisor@nats.co.uk  
<http://www.nats.aero/ais>  
neil.richmond@bfs.aero (Content - Belfast Aldergrove)

### Date Of Publication

28 Jul 2022

### Notes

- (a) All times are UTC.
- (b) References are to the UK AIP.
- (c) Information, where applicable, should also be used to amend appropriate charts.



## BELFAST ALDERGROVE (EGAA) - STEEL PLATES ON TAXIWAY BRAVO

- 1 Steel Plate Covers defective surface on TWY Bravo, 20 M South of Bravo Holding Point, 3 M West of Centreline.
- 2 Steel Plate Covers defective surface on TWY Bravo, 20 M North of Bravo Holding Point, directly over TWY Centreline.

